



Safety Message of the Day for IMEA Members



Position Yourself for the Unexpected

Good positioning can reduce the consequences when equipment doesn't operate as expected. When switching or working around equipment with arc-flash potential, keep your body out of the likely arc path, maintain required approach distances, use appropriate PPE, and avoid standing directly in front of doors or covers when possible.

Plan your position for what could go wrong - not just for what you expect to happen.