



Know Your Hazard Level

Never assume the risk. Check labels, review job plans, and confirm the arc flash boundary and PPE requirements. Matching your PPE to the hazard level keeps you protected and compliant.